SSIT SECURITY LOCATION

BERTH 1   BERTH 2

000   1+100   1+200   1+300   1+400   1+500   1+600

SSIT Security Manager
Spot Checking

K   M   N   P   R   S   U   V

SSIT
Weigh
Bridge
(WB)

WS
PWT

DA GATE
CHECK
IN - OUT

Customer office

Main Gate

STOP
CHECK-OUT

STOP!
CHECK-IN

MANAGEMENT OFFICE

Enter

1. Give security his Driver License, ID
   and Truck Registration Card
2. Security check Preregistered List
3. Security hand out Vistor Card
Step 1,2 & 3 must be completed before open the barrier

Exit

Must present an Approval Receipt & Stamp from PWT

Legend

- 🔵 Permanent security
- 🟡 SSIT Staff
- 🟠 Increase as needed

965 Road